

INTEGRATED
Environmental Services, Inc.

April 30, 1997

Mr. James E. Ross, P.E.
Unit Chief, Site Cleanup Unit
Regional Water Quality Control Board
Los Angeles Region
101 Center Plaza Drive
Monterey Park, CA 91754-2156

Re: Soil Stockpile Report, Parcel A, Report No. 1
McDonnell Douglas C-6 Facility, Los Angeles, CA


Dear Mr. Ross:

On behalf of McDonnell Douglas Realty Company, I am pleased to submit the subject report for your review and approval. The report was prepared by Montgomery Watson, the on-scene environmental consulting firm for the project.

As you have witnessed in your frequent site visits, site characterization and cleanup of Parcel A of the C-6 Facility follows the *Sampling and Analysis Plan for Demolition Activities at the Douglas Aircraft Company C-6 Facility* submitted to the Water Board. This report presents results of comprehensive analytical analyses confirming the soil stockpiles B37-RE-1, B37-RE-2, B37-RE-3, and Volcano Project soil stockpile are suitable for use as backfill. Portion of the soil stockpile B37-RE-4 contains chemical concentrations exceeding the site-specific health based screening criteria, and will be removed and disposed of at an off-site permitted disposal facility. The remaining B37-RE-4 stockpile soils are deemed suitable for on-site backfill.

I appreciate the opportunity to work closely with you and your staff on this important project. Your expedited approval of the request is appreciated.

Sincerely yours,


Michael Y. Young, Ph.D.
President
Integrated Environmental Services, Inc.

cc: Karen Thomas Baker, DTSC
Mario Stavale, MDRC
Project File